

20MY MHEV P6 ENGINE - RANGE ROVER AND RANGE ROVER SPORT LOW SPEED DRIVABILITY CONCERNS



- Product Investigation are receiving a number of reports of low speed engine drivability concerns on 20MY Range Rover and Range Rover Sports with MHEV AJ20P6 cylinder engines.
- Customers may report that below 3 mph the transmission shifter flashes D and engine stops as if in a stop-start event. The engine can be restarted immediately and the vehicle will then operate as normal.
- This issue is being urgently investigated by Product Engineering who are requesting all such cases are reported to ensure all relevant data is collated in support of a robust fix.
- This concern seems to be only affecting vehicles in hot humid areas however should this customer concern be reported at any location, Retailers are requested to submit a TA case containing details of all the customer symptoms and diagnosis performed.

