

Range Rover Sport Poor Cabin Heat Performance	19MY RR Sport equipped with AJ20P6
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none"> • The cabin does not get warm enough. <p><u>Technical Description:</u></p> <ul style="list-style-type: none"> • Restricted coolant flow into the heater core caused by a twisted coolant hose. <p><u>Status:</u></p> <ul style="list-style-type: none"> • Changes have been made at the point of assembly to mitigate the risk of this condition. • Inspect the coolant hose that flows into the heater core. • If identified as twisted, replace the hose as necessary. 	