

Engine Speed Instability at low RPM

19/20 MY Range Rover and RR Sport equipped with AJ20P6

Customer Voice:

- The engine runs rough at idle.
- The vehicle stalled, the vehicle could be restarted on the next ignition cycle.

Technical Description:

- The condition may be experienced at various speeds with low engine RPM.
- The vehicle can be restarted on the next ignition cycle.

Status:

- A revised PCM and TCM calibration is available to address this condition.
- Complete diagnosis/repair of any DTCs that are identified in the vehicle.
- Once complete or if no DTCs are stored, raise a TA so a manual patch can be created to install the updated calibration.
- ETA for the software into Pathfinder is CW 48.

