



AJ20 VCT Solenoid Replacement	18MY Onward Discovery Sport, RR Evoque, RR Velar, XE, XF, F PACE, E PACE, F TYPE
<p><b><u>Customer Voice:</u></b></p> <ul style="list-style-type: none"><li>• The Check Engine MIL is on.</li></ul> <p><b><u>Technical Description:</u></b></p> <ul style="list-style-type: none"><li>• DTC P054A-00, P0014-00, P000B-00 may be stored in the PCM.</li></ul> <p><b><u>Status:</u></b></p> <ul style="list-style-type: none"><li>• If the VCT solenoid is identified as the cause and requires replacement, ensure the parts outlined for your VIN in EPC are being used including any part supersession.</li><li>• A revised part will be outlined for gasoline engines only.</li><li>• The revised part can be identified by the last two characters of the WERS number being AB as well as 3 drain holes.</li></ul>	

