

Blower Motor Operation	2018 Onwards Range Rover, Range Rover Sport and Discovery
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none"> • There is no air flow from the HVAC system. <p><u>Technical Description:</u></p> <ul style="list-style-type: none"> • Blower motor inoperative due to a blown fuse 5E in the EJB. (engine junction box) <p><u>Status:</u></p> <ul style="list-style-type: none"> • Under investigation. • Should diagnosis lead to the replacement of the fuse/blower motor, please raise an EPQR with the parts managers information for us to create a parts return. 	 