



Preliminary Information

PIP5658A Heat Shrink Hose Clamp Information

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 4500HD 5500HD 6500HD	2019	All	All	6.6L L5D	All

Involved Region or Country	North America
Condition	There may be a concern where coolant heat shrink clamps need to be replaced for a coolant leak and/or for a service repair.
Cause	Difficult to get the heat shrink clamps to seal the coolant hose.

Correction:

When possible use the heat shrink clamps in the places that they are called for.



Heat shrink clamp

There may be location that may not be accessible to get a heat gun to.

For locations that are inaccessible to a heat gun, use hose clamp p/n 19404911, torque @ 9-11 Nm (79 - 97 lb in).

This PI will be deleted as Service information is updated.

Version History

Version	1
Modified	06/10/2019 - Created on 11/20/2019 - Updated to correct part number in Condition Section.



© 2019 General Motors. All Rights Reserved.