



Bulletin No.: PIP5689  
Published date: N/A

## Preliminary Information

### PIP5689 3.0L LM2 Diesel Engine With Malfunction Indicator Lamp Illuminated With One Or More DTCs Set. P2B60, P1010

#### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 1500	2020	All	All	3.0 LM2	All
GMC	Sierra 1500	2020	All	All	3.0 LM2	All

Involved Region or Country:	North America
Condition:	Malfunction Indicator Lamp Illuminated
Cause:	There is a software anomaly in the engine calibration that can falsely set DTCs P2B60 or P1010

#### Correction:

**Note:** Stable battery voltage is critical during programming. Any fluctuation, spiking, over voltage or loss of voltage will interrupt programming. Install a GM Authorized Programming Support Tool to maintain system voltage. Refer to <https://www.gmdesolutions.com> for further information. If not available, connect a fully charged 12 V jumper or booster pack disconnected from the AC voltage supply. DO NOT connect a battery charger.

Reprogram the ECM with the latest calibration.

#### Warranty Information

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation:	Description:	Labor Time:
4087258	ECM program to correct DTCs P2B60 and P1010	0.3 hour

#### Version History

Version	1
Modified	11/26/2019 - Created on.



GENERAL MOTORS

© 2019 General Motors. All Rights Reserved.