

Type: Satisfaction Campaign

Year: 2019

System: Engine (12)

Sequence: 01

First Release Rev: 0.1

Title: Sensor Protection Cap Install

Applicability: MY20 Revero GT Demos

Market Region: All

PRIORITY: Vehicles on list

PURPOSE:

The throttle body sensor connector under the engine cover has been issued a protective cap. The cap will prevent a sagging engine cover and protect the wiring. This applies to the vehicles listed below.




50GK43SB3LA000010	50GK43SB7LA000026
50GK43SB8LA000021	50GK43SB0LA000028
50GK43SB1LA000023	50GK43SB2LA000029
50GK43SB3LA000024	50GK43SB4LA000033
50GK43SB5LA000025	50GK43SB6LA000034


Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

Title: Sensor Protection Cap Install**Applicability:** MY20 Revero GT Demos**Market Region:** All**Type:** Satisfaction Campaign**Year:** 2019**System:** Engine (12)**Sequence:** 01**First Release Rev:** 0.1

1. Open the hood, remove the engine cover.
Locate the connector indicated below (Fig. 2).



3. Remove the connector- pull up the white tab and
remove connector (Fig. 3).



Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

Type: Satisfaction Campaign

Year: 2019

System: Engine (12)

Sequence: 01



First Release Rev: 0.1

Title: Sensor Protection Cap Install


Applicability: MY20 Revero GT Demos

Market Region: All

4. Add the protection cap (shown below Fig. 4a) to the connector (Fig. 4b). This clips around the connector in a clam-shell fashion.



5. Connect this back to the sensor and push down the white tab. (Fig. 5). Reinstall the engine cover.



Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

Type: Satisfaction Campaign

Year: 2019

System: Engine (12)

Sequence: 01

First Release Rev: 0.1

Title: Sensor Protection Cap Install

Applicability: MY20 Revero GT Demos

Market Region: All

PARTS REQUIRED:

PART NUMBER	DESCRIPTION	QUANTITY
C171000001438	Protection Cap	1

SHOP SUPPLIES if Required:

PART NUMBER	DESCRIPTION	QUANTITY
N/A		

SPECIAL TOOLS:

DESCRIPTION
N/A

CAUSAL PART:

PART NUMBER	DESCRIPTION
C131179001900	Cover Assembly - Engine

LABOR CODES:

CODE	DESCRIPTION	TIME	DEFECT CODE
12-70-07-05	Protection cap install	0.3	12-70-07-32

SUBLET:

CODE	DESCRIPTION	AMOUNT
N/A		

WARRANTY DISPOSITION: This repair is covered under the New Vehicle Limited Warranty, in effect for four (4) years from the in-service date with no mileage limitation.

Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.