

GPOP - Issue Review System

Part Number: 82215312A\$, 82215613A\$, 82215612A\$

Part Description: WIRING KIT, Enclosure (Mopar JL hard top conversion accessory kit)

Issue Description: The HVAC control panel requires replacement when GTP sales code is present to restore rear defrost function. The switch is not provided in this kit and a service replacement part must be ordered.

See service information procedure for switch replacement and below chart for replacement part numbers.

vehicle has GTP+BNH+HAA replace HVAC control with pn 6BE36TRMAC
vehicle has GTP+BNH-HAA replace HVAC control with pn 6BE37TRMAC
vehicle has GTP+HAA-BNH replace HVAC control with pn 6BE40TRMAC
vehicle has GTP-HAA-BNH replace HVAC control with pn 6BE41TRMAC

Please ensure that the proper color code is used in place of the part TRM designation.

For any questions call John Altsman at (248) 512-9361.

~ _____ ~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.