

**NUMBER:** 08-007-19 REV. A

**GROUP:** 08 - Electrical

DATE: November 6, 2019

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

This bulletin supersedes Service Bulletin 08-007-19, dated January 25, 2019, which should be removed from your files. All revisions are highlighted with \*\*asterisks\*\* and include updated build dates and converting to an RRT.

\*\*This Service Bulletin is also being released as Rapid Response Transmittal (RRT) 19-091, dated November 06, 2019. All applicable Sold and Un-Sold RRT VINs have been loaded. To verify this RRT service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.\*\*

## SUBJECT:

Flash: Electric Power Steering (EPS) Module Enhancements - AN-K8-19-20191030

## **OVERVIEW**:

Refer to China Joint Venture (JV) released document AN-K8-19-20191030, for details on this service action.

## MODELS:

2019

(K8)

Jeep Grand Commander (China)

- NOTE: This bulletin applies to vehicles within the following markets/countries: APAC (China only).
- NOTE: This bulletin applies to vehicles built on or after \*\*March 28, 2018 (MDH 0328XX) and on or before October 20, 2019 (MDH 1020XX)\*\* equipped with a 2.0L I4 DOHC DI Turbo Engine W/ ESS (Sales Code EC1).

## **Policy:**

Information Only