

Service Bulletin

Bulletin No.: 16-NA-058

> Date: November, 2019

TECHNICAL

Brake Grinding Noise Heard and/or Grooved Rotors - 1st Design / 2nd Design Brake Subject:

Caliper Assemblies

	Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
			from	to	from	to	Eligilie.	mansinission.
ĺ	Buick	Regal	2016	2016	SOP	G9120774		

Condition	Some customers may comment on a grinding noise heard when applying the brakes. Upon further inspection, a technician may find the brake pads are worn and the rotors have grooves.	
Additional Options	BRAKE SYSTEM-POWER, FRT & RR DISC, ABS, 17" (RPO J61)	
Correction	Replace the 1st design brake calipers and brackets with the 2nd design and install new brake pads. Note: Replace rotors as needed due to being grooved.	

Service Procedure

Refer to Front Disc Brake Pads (J60, J61) and Front Brake Caliper Replacement (J60, J61) in SI.

Parts Information

Refer to the electronic parts catalog (EPC) for the correct parts information.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2420150	Front Disc Brake Pads Replacement	Use Published
2420530	Front Brake Caliper Replacement	Labor Operation Time

Version	3
Modified	March 3, 2016 – Included replacing the bracket in the Correction and removing the graphics. November 12, 2019 – Updated an SI procedure reference in the Service Procedure and updated the Warranty Information.

