

Subject		Market
Body Electronics Inoperative - D/C Cut Fuse		USA
Service Category	Section	
Vehicle Interior	Meter/Gauge/Display	
Applicability		
2018-2020 LS500		

APPLICABLE VEHICLES

2018-2020	LS500
-----------	-------



CONDITION

If the D/C Cut Fuses are not properly seated in the correct main relay block location, multiple body electronic systems can be affected. Some systems that may become inoperative or operate abnormally due to a loose or missing D/C Cut Fuse are listed below:

- Clock
- Wireless Door Lock Control (Locks/unlocks vehicle by electrical key)
- Smart Access System (Locks/unlocks vehicle by touching the door handle)
- Power/Heated/Cooled/Massaging Seats
- HomeLink Door Opener

RECOMMENDATIONS

When diagnosing body electrical systems, such as the ones listed above, best practice is to confirm that the D/C Cut Fuses and other related fuses are checked for continuity, proper seating, and correct location.



LINK REFERENCES

This Tech Tip does not contain any link references