



# Service Bulletin

Bulletin No.: 19-NA-266

Date: November, 2019

## TECHNICAL

**Subject:** Flutter Noise Emitting from Center of Vehicle

| Brand:    | Model: | Model Year: |      | VIN: |    | Engine:            | Transmission: |
|-----------|--------|-------------|------|------|----|--------------------|---------------|
|           |        | from        | to   | from | to |                    |               |
| Chevrolet | Camaro | 2016        | 2019 |      |    | 6.2L<br>(LT1, LT4) |               |

|                                   |   |
|-----------------------------------|---|
| <b>Involved Region or Country</b> | North America, N.A. Export Regions  |
| <b>Condition</b>                  | Some customers may comment that a flutter type noise is emitting from the center of the vehicle or from the console/shifter area. |
| <b>Cause</b>                      | This condition may be caused by a damaged propeller shaft center support bearing.   |
| <b>Correction</b>                 | If the center bearing has been found to be the cause of the noise, replace the center support bearing.                            |

### Service Procedure

Refer to *Propeller Shaft Center Support Bearing Replacement* in SI.

### Parts Information

| Causal Part | Engine          | Description                   | Part Number | Qty |
|-------------|-----------------|-------------------------------|-------------|-----|
| X           | LT1 (2016-2019) | BEARING, PROP SHF<br>CTR SUPT | 84515638    | 1   |
| X           | LT4 (2017-2019) | BEARING, PROP SHF<br>CTR SUPT | 84470372    | 1   |

### Warranty Information

For vehicles repaired under warranty, use:

| Labor Operation | Description  | Labor Time                         |
|-----------------|--|------------------------------------|
| 3020010         | Propeller Shaft Center Support Bearing Replacement | Use Published Labor Operation Time |

|                 |                            |
|-----------------|----------------------------|
| <b>Version</b>  | 1                          |
| <b>Modified</b> | Released November 19, 2019 |

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY  
TECHNICIAN  
CERTIFICATION