

Subject: Engineering Information – Oil Leaking From Oil Pan

This PI has been revised to end the need for information from the field. Please discard PIE0536.

| Brand: | Model: | Model Year: | | VIN: | | Engine: | Transmission: |
|-----------|-------------------------------|-------------|------|------|----|--|---------------|
| | | from | to | from | to | | |
| Chevrolet | Silverado 1500 (New Model) | 2019 | 2019 | - | - | Equipped with 2.7L Engine (RPO L3B) | - |
| | Silverado 1500 | 2020 | 2020 | | | | |
| GMC | Sierra 1500 (New Model) | 2019 | 2019 | | | | |
| | Sierra 1500 | 2020 | 2020 | | | | |

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

| | |
|-----------------|---|
| Version | 2 |
| Modified | Released September 13, 2019 Revised November 12, 2019 – Ended the need for further information from the field. |