

Subject: Engineering Information – Stick-Slip Type Condition Felt in Steering Wheel at Highway Speeds

This PI has been revised to end the need for information from the field. Please discard PIE0539A.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	LaCrosse	2017	2019	-	-	-	-
	Regal	2018					
Cadillac	XT4	2019					
Chevrolet	Malibu	2016					

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	3
Modified	Released September 17, 2019 October 01, 2019 – Updated the Condition and Correction sections. November 25, 2019 – Ended the need for further information from the field.