

Subject UA80/UB80 Transmission Side Cover Leak		Market USA
Service Category Drivetrain	Section Automatic Transmission/Transaxle	
Applicability Multiple Model UA80/UB80		

APPLICABLE VEHICLES

2018-2020	Highlander	2018-2019	Sienna
2019-2020	RAV4	2018-2020	Camry
2019-2020	Avalon		

CONDITION

Some 2018-2020 model year UA80/UB80 transmission equipped models may experience a leak from the Transmission Side Cover. This issue is currently under investigation. Vehicles are being sought regardless of months in service or mileage. Only seeking vehicles with leaking transmissions with no other signs of damage to the side cover.

RECOMMENDATIONS

Please create a TAS case and contact TAS for instruction prior to diagnosing or repairing of the vehicle. If it is a weekend or holiday, continue with diagnosis and repair. Please save all parts and/or details and contact TAS on the next available work day.

LINK REFERENCES

This Tech Tip does not contain any link references