

Subject <b>DTC B15A8 - DCM System Internal Failure</b>		Market <b>USA</b>
Service Category <b>Audio/Visual/Telematics</b>	Section <b>Cellular Communication</b>	
Applicability <b>All Applicable Models</b>		

**APPLICABLE VEHICLES**

2020	RAV4	2020	Camry
2020	Corolla Hatchback	2020	RAV4 HV
2020	Camry HV		

**CONDITION**

Some 2020 model year Camry, Camry HV and Corolla Hatchback vehicles equipped with a DCM may exhibit a B15A8\*\* DTC in history during PDS. This DTC can be triggered during the manufacturing and /or shipping process and does not indicate a problem with the vehicle. To simplify the diagnosis of this DTC, refer to the procedure below to prevent unnecessary parts replacement.

**RECOMMENDATIONS**

Is the DTC current or a history DTC?

- History – Clear the DTC
- Current and red SOS light is on - Disconnect the 12V battery for 30 minutes to reset/initialize the DCM
  - If the green SOS light is on, normal operation has been restored
  - If the condition has not changed, please diagnose per the repair manual.

**LINK REFERENCES**

This Tech Tip does not contain any link references