News Channel Update |

Vehicle Compliance & Analysis

	TO: Mercedes-Benz Dealer Principals, General Managers, Sales	FROM: Gregory Gunther, Department Manager, Vehicle	
	Managers, Service Managers, Parts Managers	Compliance and Analysis, Engineering Services	
	RE: Service Campaign Launch Notification		
Update AMG Suspension Control Unit Software		DATE: November 8, 2019	
	MY15-19 205 213 253 (C-Class, E-Class and GLC-Class)		

IMPORTANT SERVICE CAMPAIGN INFORMATION

Please see the attached documents related to the campaign listed above.

Please note that all customer inquiries should be directed to the Customer Assistance Center at 1-800-FOR-MERCEDES.

Sincerely,

Gregory Gunther

Department Manager, Vehicle Compliance & Analysis



Vehicle Compliance & Analysis

Service Campaign	Launch Notification	November 8, 2019	
Campaign No. :	Campaign Desc. :	Update AMG Suspension Control	
2019100004	19P5499604	Unit Software	
		G suspension control unit software on <u>9,569</u> Model Year ("MY") (253 platform) vehicles. The vehicles will be visible and flagged in ember 8, 2019.	
	Backgrou		
Issue	Model Year ("MY") 2015-20 (253 platform) vehicles, the	Daimler AG ("DAG"), the manufacturer of Mercedes-Benz vehicles, has determined that on certain Model Year ("MY") 2015-2019 C-Class (205 platform), E-Class (213 platform), and GLC-Class (253 platform) vehicles, the AMG suspension control unit software might not meet current production specifications. The possibility exists that noise development may arise in the area of the rear axle differential.	
What We're Doing		MBUSA will conduct a service campaign. An authorized Mercedes-Benz dealer will update the AMG suspension control unit.	
Parts	The remedy is available an	The remedy is available and can be performed.	
	Vehicles Aff	fected	
Vehicle Model Year(s)	2015-2019	2015-2019	
Vehicle Model	C-Class, E-Class and GLC-Cla	C-Class, E-Class and GLC-Class	
	Vehicle Popu	llations	
Total Campaign Population	9,569	9,569	
	Next Steps/	'Notes	
AOMS/SOMS	AOMs – This campaign may g your dealers ASAP.	generate questions from your dealers. Please forward this notice to	
9 ,	•	o maintain a high level of vehicle quality and customer satisfaction. Assistance Center at 1-800-FOR-MERCEDES.	



Service Campaign Bulletir

Service Campaign Bulletin

Service Campaign Bulletin



Campaign No. 2019100004, November 2019

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: Model C-Class, E-Class, and GLC-Class (205 213 253 platform)

Model Years 2015-2017

Update AMG Suspension Control Unit Software

Mercedes-Benz ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has determined that on certain Model Year ("MY") 15-17 C-Class, E-Class, and GLC-Class (205, 213, and 253 platform) vehicles, the software of the AMG suspension unit might not meet current production specifications. The possibility exists that noises may develop in the area of the rear axle differential. An authorized Mercedes-Benz dealer will update the software of the AMG suspension control unit on the affected vehicles.

Prior to performing this Service Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired. Always Check VMI for any open campaigns, and perform accordingly.
- Please review the entire Service Campaign bulletin and follow the repair procedure exactly as described.

Approximately 9,592 vehicle is affected.

Order No. P-SC-2019100004

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

Procedure

- Use Xentry 9/19 with all associated patches or higher.
- Follow the steps exactly as described in Xentry.
- Connect battery charger (battery voltage >12.5V).
- Ensure all electrical consumers are switched-off.
- In the event of software/SCN update issues, contact Star Diagnosis User Help Desk via. XSF ticket.
- Refer to Star Diagnosis System (SDS) Best Practices Guide.
- 1. Connect XENTRY Diagnosis.
- 2. Update AMG suspension control unit software.

To do this, select menu item "Quick test view N3/43 AMG suspension (AMG FW) Adaptations Control unit update Update of control unit software".

 $oxed{f i}$ Then follow the user guidance in XENTRY Diagnosis.

3. Disconnect XENTRY Diagnosis.

Warranty Information

Operation: Connect/disconnect battery charger (02-5058)

Star Diagnosis System (SDS), Connect/disconnect (02-4762)

Update AMG suspension control unit software (XENTRY Diagnosis connected)(02-9334)

Damage Code	Operation Number	Labor Time (hrs.)
54 996 04 8	02-5058	0.1
	02-4762	0.1
	02-9334	0.1

Operation Number labor times are subject to change