

PSM Fault Code OD2602

Vehicles Affected

Model	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
Macan	2019	95B	N/A	N/A

Revision History

Revision	Release Date	Changes
0	December 6, 2019	Original document

Customer Concern

If the customer reports, or you confirm, a temporary brake warning in white text, fault code OD2602 may be set.

Technical Information

During cold engine start, or brake pedal actuation during engine stop, the vacuum change in the brake system may be enough to set this fault. It does not cause performance issues and is not a safety concern for the customer. The pressure monitoring threshold was just a bit too narrow and has been widened.

Production Solution

The PSM software with a wider pressure monitoring threshold has been in production since July of 2019.

Warranty

No repairs are necessary at this time.

Search Items

PSM; OD2602; vacuum; brake; pressure

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.