

**SSM 48388 - 2020 Mustang - U3000:62 Diagnostic Trouble Code (DTC) In The Power Steering Control Module (PSCM) – Built On Or Before 04-Sep-2019**

Some 2020 Mustang vehicles built on or before 04-Sep-2019 may exhibit a U3000:62 DTC set in the PSCM. This may be accompanied by a slightly different steering feel, which will return to normal after one key cycle. To correct this condition, update the PSCM using the latest software level of the appropriate Ford diagnostic scan tool. For claiming use causal part 3504 and applicable labor times in Section 10 of the Service Labor Time Standards (SLTS) Manual.