

Technical Service Bulletin

Topic	Infotainment screen turns red sporadically
Market area	Bentley: worldwide (2WBE),Hongkong-Macau (5HK)
Brand	Bentley
Transaction No.	2055846/2
Level	EH
Status	Released for publishing
Release date	Dec 16, 2019

New customer code

Object of complaint	Complaint type	Position
information, navigation, communication, entertainment -> radio, navigation, MMI and drive device functions	functionality	
information, navigation, communication, entertainment -> instrument cluster, displays, screens	functionality	

Vehicle data

New Continental GT and New Continental GTC

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
3S3*	2018	E		*	*	*
3S3*	2019	E		*	*	*
3S3*	2020	E		*	*	*
3S4*	2019	E		*	*	*
3S4*	2020	E		*	*	*

New Flying Spur

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
ZG2*	2020	E		*	*	*

Documents

Document name
master.xml



Condition

Infotainment screen turns red sporadically (Figure 1)



Figure 1

Technical Background

Refer to Measure section of this TPI

Production Solution

Under investigation

Service

Reset the Infotainment system as follows:

- Press and hold the volume rotary switch (Figure 2) for 10 seconds



Figure 2

Additional Information

- Following the reset of the system the issue should not re-occur