



Technical Journal

TITLE:

DIM message about parking brake

REF NO: TJ 34647.4.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2019-12-06	STATUS DATE: 2019-12-10
FUNC GROUP: 5930	FUNC DESC: Anti-lock brake (anti-skid)	Page 1 of 2	

“Right first time in Time”

Attachment

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
224							2019-2020		0000448-0049447	201835-201945
234							2017-2020		0000350-0082542	201617-201945
235							2017-2020		0000160-0133860	201624-201945
236							2017-2020		0000098-0108654	201646-201945
238							2017-2020		0000161-0161856	201646-201945
246							2017-2020		0000389-0511603	201717-201945
256							2016-2020		0000561-0578773	201505-201945

CSC Customer Symptom Codes

Code	Description
IV	Text window and warning symbol/Text message
PK	Parking brake/No/reduced/incorrect function

VST Operation Number

VST Operation Number	Description
36004-2	Software control module downloading



DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
BCM	B111177	Intermittent
BCM	B111167	Intermittent
SRS	U2C8692	Intermittent

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Text

DESCRIPTION:

*Added Vehicle Type information

If the DIM message “Parking brake not fully released” or “Auto Hold service required” is present in combination with any of the DTC’s, please follow instructions under “Service”.

SERVICE:

1. Verify the symptom and DTC’s.
2. Perform a software upgrade in accordance with TJ 31543.

Warranty claim info:

To get warranty claim accepted for a job described in this TJ, please use following data:
VST OP number: 36004-2 and relevant CSC.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area “Vehicle Report” and sub concern area “Support Needed”, use function group 5930.