

## GPOP - Issue Review System

**Part Number:** 68166623A\$

**Part Description:** CABLE, Gearshift Control

**Issue Description:** If you are replacing a transmission shift cable on a VF ProMaster vehicle built with a 3.6L engine, for binding/kinked/seized or broken cable please take a picture of the shifter end of the cable, from the bottom of the cable mounting clip to the shifter end of the cable, also take a picture of the 4 digit code printed in white on the outer covering of the cable. Send pictures with VIN to Bob Henderson at bob.henderson@fcagroup.com.

~ \_\_\_\_\_ ~  
Contact Us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related to this GPOP Tech Tip. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.