

GPOP - Issue Review System

Part Number: 68421577A\$, 68421578A\$

Part Description: Latch, Quarter Window, Power Sliding Roof

Issue Description: Prior to ordering this part for customers that complain about a buzz, squeak, or rattle, please reference the repair information in the service library. Latch rattles can be repaired by applying UHMW tape to the receiver.

~ _____ ~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.