

Bulletin No.: PIT4297A Published date: 12/11/2019

Preliminary Information

PIT4297A Rattle or Clunk Noise From Front Of Vehicle Over Bumps

<u>Models</u>

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to	Engine.	Transmissions.
Buick	Rainier	2004 - 2008	All	All	All	All
Chevrolet	Trailblazer	2002 - 2009	All	All	All	All
Chevrolet	Trailblazer EXT	2002 - 2009	All	All	All	All
Chevrolet	Trailblazer SS	2002 - 2009	All	All	All	All
GMC	Envoy	2002 - 2009	All	All	All	All
GMC	Envoy XL	2002 - 2009	All	All	All	All
GMC	Envoy EXV	2002 - 2009	All	All	All	All
Oldsmobile	Bravada	2002 - 2004	All	All	All	All
Saab	97x	2005 - 2008	All	All	All	All

Supersession Statement

This PI was superseded to update Model Years. Please discard PIT4297.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition / Concern

Some customers may comment of a rattle or clunk noise from the front of the vehicle. This noise can be easily mistaken for a front suspension component or stabilizer links. The noise may be the result of the hood rattling within the hood latch or at the front corners of the hood.

Recommendations / Instructions

1. Lubricate the center hood latch and the hood bumpers at the front corners. Re-evaluate the concern.

2. If the noise is still present, adjust the hood latch to draw the hood tighter to the body. Reevaluate the concern

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.



© 2020 General Motors. All Rights Reserved.