

Subject: Engineering Information – Wheel Speed Sensor Inoperative, DTCs C0035, C0040, C0045 and/or C0055 Set

This EI has been revised to end the need for information from the field. Please discard PIE0533.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Malibu	2019	2020	-	-	-	-
	Impala						

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released August 13, 2019 December 11, 2019 – Ended the need for further information from the field.