

Complaint of noise from area of steering column

Topic number	LI46.15-P-070510
Version	1
Function group	46.15 Steering column adjustment
Date	12-03-2019
Validity	Model 177 Model 247 Model 118
Reason for change	
Reason for block	

Complaint:

Noises from the area of the steering column.

- Creaking
- Squeaking
- Chattering
- Humming
- Grinding

Cause:

Possible outside influence or other cause.

Remedy:

Check surrounding area of the steering column for possible noises.

- Instrument panel support
- Steering column switch module

If the cause of the noise can be narrowed down to the steering column, create a PTSS case.

Attach a detailed description of the noise complaint and a video/audio recording of the noise.

Symptoms
Chassis/suspension / Steering system / Noises / Beeping
Chassis/suspension / Steering system / Noises / Dragging/squealing
Chassis/suspension / Steering system / Noises / Cracking
Chassis/suspension / Steering system / Noises / Hissing/streaming
Chassis/suspension / Steering system / Noises / Chattering/knocking

XENTRY TIPS

Chassis/suspension / Steering system / Noises / Humming/vibrations
Chassis/suspension / Steering system / Noises / Clattering
Chassis/suspension / Steering system / Steering column adjustment / Clattering
Chassis/suspension / Steering system / Steering column adjustment / Corrosion
Chassis/suspension / Steering system / Steering column adjustment / Knocks