

WORK DESCRIPTION FOR FIELD MEASURE

Code: 19P5499001

Version: 2.0

Update stereo multifunction camera control unit software

Models 217; 222

- i** • Ensure use of **XENTRY Diagnosis version** BD/DVD (**07/2019**) or higher.
- Before starting the work procedure, install all the **add-ons that are updated daily** in **XENTRY Diagnosis**.
- Please make sure to follow the operation steps exactly as described in XENTRY Diagnosis.
- Use a battery charger to ensure sufficient power supply of the vehicle **on-board electrical system battery** (greater than 12.5 V).
- If XENTRY Diagnosis is already connected to the vehicle, start with **operation step 2**.
 - i** If two or more software updates or SCN codings are performed during one workshop visit the operation items 02-4762 and 02-5058 may be invoiced **only once for each workshop order!**

Work procedure

1. Connect XENTRY Diagnosis.
2. Update control unit software or A40/13 (stereo multifunction camera).
 - i** To do so, select menu item "Quick test view – A40/13 (stereo multifunction camera) – Adaptations – Control unit update – Update of control unit software".
 - i** Then follow the user guidance in XENTRY Diagnosis.
3. Disconnect XENTRY Diagnosis.

Operation text and flat rate

Operation no.	Operation text	Flat rate	Accounting no./ damage code
02-9334	Update stereo multifunction camera control unit software (XENTRY Diagnosis connected)	0.1 h	54 990 01
02-4762*	Connect/disconnect vehicle diagnosis system (XENTRY Diagnosis)	0.1 h	54 990 01
02-5058*	Connect/disconnect starter battery charger (with XENTRY Diagnosis connected)	0.1 h	54 990 01

* Operation item may be invoiced only once for each workshop order!

Mercedes-Benz
Global Service & Parts