



# Service Bulletin


Bulletin No.: 17-NA-302

Date: December, 2019


## INFORMATION

**Subject: Dust, Snow or Water Around Fuel Filler Area**

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado	2017	2018				
	Silverado LD	2019	2019				
	Silverado 2500/3500						
GMC	Sierra	2017	2018				
	Sierra Limited	2019	2019				
	Sierra 2500/3500						

<b>Involved Region or Country</b>	North America, Middle East, Israel, Chile and Thailand.
<b>Condition</b>	Some customers may comment on excess amount dirt, snow or water that can build up around the fuel filler neck.
<b>Cause</b>	This condition may be caused when trucks are operated in high amount of dirt, dust or snow which can migrate to the filler cap area.
<b>Correction</b>	<p><b>Locking Gas Cap</b></p> 

4869504

	<p style="margin: 0;"><b>Non - Locking Gas Cap</b></p> <div style="text-align: center; margin: 10px 0;">  </div> <p style="text-align: right; margin: 0; font-size: small;">5458913</p> <p style="margin: 10px 0;">Notify the customer that GM has made available a gas cap for drivers that operate in these environments. This will help to protect the fill area and the fuel system.</p>
--	--

**Parts Information**

Causal Part	Description	Part Number	Qty
X	CAP ASM-F/TNK FIL LKG	84009129 (2017)	1
		84308352 (2018–2019)	
	CAP ASM - F/TNK FIL (Non Locking)	84689444 (2017 - 2019)	

<b>Version</b>	4
<b>Modified</b>	<p>Released January 11, 2018</p> <p>Revised February 15, 2018 – Updated information under the Subject, Condition, Cause and Correction.</p> <p>Revised January 15, 2019 – Added 2019 Silverado LD, Silverado 2500/3500, Sierra Limited, Sierra 2500/3500 and updated the Parts Information.</p> <p>Revised December 12, 2019 – Added Parts Information for available Non-Locking gas cap.</p>

