

Document Information

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.

Vehicles affected: P13R: 600LT, 600LT Spider

Location: Body - Exterior

Concern: 600LT vehicles delivered without Side Intake Duct Grilles

Condition: Part not present

Diagnostic Trouble Codes

N/A

Measure

All 600LT variants are manufactured without the Side Intake Duct Grilles (present in other P13 variants). The absence of these grilles is intentional. They have been removed from this vehicle's design for aerodynamic and cooling efficiency purposes.

Care Point:

Currently the Spare Parts Catalogue in the Retailer Portal depicts the grilles in the relevant field as part of the drawing. This will be removed in a future system update. In the same illustration, no part number is listed for the grilles which is correct as the 600LT variants are not equipped with these grilles.

Do not attempt to install these during PDI.

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.