

Document Information

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.

Vehicles affected: McLaren GT

Location: Body Exterior – Ducts Vents and Floors

Concern: Guide vanes cannot be installed due to fixing hole not aligned with subframe hole

Condition: During PDI

Diagnostic Trouble Codes

N/A

Measure

If during PDI of a McLaren GT it is noticed that the internal guide vanes cannot be installed due to the fixing hole not aligning with the subframe hole, please do not attempt to install the part.



The guide vanes provided with the vehicle are not within specification and therefore should not be used.

If the incorrect Internal guide vanes are supplied with the vehicle, order 22AD173GP and 22AD174GP as replacements and claim under warranty.

MTI Updates Information

N/A

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.