



**NUMBER:** 19-002-19

**GROUP:** 19 - Steering

**DATE:** November 20, 2019

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*

**SUBJECT:**

Shimmy In The Steering Wheel After Hitting An Irregularity On The Road Surface

**OVERVIEW:**

This bulletin involves discussing an available video instructing the technicians on how to properly diagnosis and repair this issue.

**MODELS:**

2018 - 2020	(JL)	Jeep Wrangler
2020	(JT)	Jeep Gladiator

**NOTE: This bulletin applies to vehicles within the following markets/countries: North America, APAC, EMEA and LATAM.**

**DISCUSSION:**

The customer may notice a shimmy in the steering wheel after hitting an irregularity on the road surface such as an expansion joint, pothole or bump.

A video aid has been developed for this issue. Refer to the detailed service procedures available in DealerConnect> Service Library under: Service Info>19 - Steering / Linkage / Damper, Steering / Removal and Installation.

**POLICY:**

Information Only.