



Technical Journal

TITLE:
Headlamp condensation - repair method

REF NO: TJ 35078.2.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2019-09-04	STATUS DATE: 2019-09-05
FUNC GROUP: 3521	FUNC DESC: Headlamp, complete	Page 1 of 2	

“Right first time in Time”

Attachment

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
224							2019-2020	70	0000001-0038564	0-0
225							2019-2020	21	0000001-0351716	0-0
225							2019-2020	22	0000001-0352203	0-0
227							2019-2020	21	0000001-0032280	0-0

CSC Customer Symptom Codes

Code	Description
W4	Headlights/Moisture/mist on inside of lens

VST Operation Number

VST Operation Number	Description
98729	Moisture in headlamp

DTC Diagnostic Trouble Codes

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Text

**DESCRIPTION:**

If there is condensation, moisture or mist inside the headlamp lens, and leak test is performed according to TJ 34521 and if no leak is found please follow advice under Service.

SERVICE:

If no leak is found, follow repair method according to Vida, search for VCC-id VCC-516999-1.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 3521.