



Parts Bulletin

TITLE:

**S29926: ERAD Thermostat Removal
MY 2018-2019 XC60, S60 S90, XC90 T8 Models**

GROUP: 2	CAT/NO: S29926	REFERENCE BULLETINS: QB S29926	CAR MARKET: United States and Canada	
COPY TO / CIRCULATIONS (PLEASE INITIAL):			ISSUE DATE: 2019-04-23	STATUS DATE: 2019-04-23
GENERAL MANAGER	PARTS MANAGER	SERVICE MANAGER	SALES MANAGER	
				Page 1 of 1

“Right first time in Time”

Reference Bulletins: QB S29926

Volvo Car USA LLC and Volvo Car Canada LTD (Volvo) on behalf of Volvo Car Corporation, have decided to launch Service Action S29926 on certain model year 2018 – 2019 XC60, S60, S90 and XC90 vehicles.

Volvo has identified that the Electric Rear Axle Drive (ERAD) thermostat may not completely open, which can result in low or no coolant flow and a Malfunction Indicator Lamp (MIL) illuminated.

The corrective action is to replace the ERAD thermostat with a T-Connector per VIDA VCC 486557-1, and insure it is installed in the proper orientation per the VIDA illustration. It is also important to bleed the engine cooling system per VIDA to complete the repair.

Service Action S29926 affects 5,755 vehicles in the U.S. and 748 in Canada.

The following part numbers apply:

Part Number	Description	Qty
32263957	T Connector	1
31439821	Coolant	1.6