


Latest Vehicle Concern Fixes



Water Ingress From Sunroof	F-PACE, RR Velar
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">• Customers may report water leaking from the roof opening panel. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">• This may be caused by a roof cassette that has not been sealed properly during manufacturing. <p><u>Status:</u></p> <ul style="list-style-type: none">• We are currently investigation concerns of water ingress from the roof cassette.• Please report any cases found of this concern via EPQR with pictures of where the water leak point is and sealant issue.	 <p>The diagram shows a top-down view of a car's interior, specifically the sunroof area. The sunroof is highlighted in blue. Two red circles are drawn around the sunroof's perimeter, indicating potential areas for water ingress. Two small black arrows point downwards from the sunroof's edge, suggesting the direction of water flow.</p>

