

> Constellation  
> 4700 Models  
> 4800 Models  
> 4900 Models

> 5700 Models  
> 5900 Models  
> 6900 Models  
> Heritage

**Western Star  
Service Bulletin**

**Description of Revisions:** *This bulletin replaces the version dated 10/01/2006. The 4700, 4800, 4900, 5700, 5900, and 6900 have been added to the model list.*

## Receiver-Drier Replacement Guidelines

Western Star does not recommend periodic maintenance of the receiver-drier.

NOTE: The following guidelines do not replace normal maintenance of the HVAC system which may vary by application and customer discretion.

The receiver-drier must be replaced if one of the following occurred:

- The refrigerant system experienced catastrophic failure that put debris into the system—this debris may have been from an internal failed part within the A/C compressor, or from a breakdown of the desiccant within the receiver-drier.
- The refrigerant system was empty due to a system leak when the vehicle arrived for service, confirmed by zero pressure at the A/C system service ports.

The two conditions above are the only circumstances in which the receiver-drier is covered if normal warranty applies. Under all other circumstances, the receiver-drier is considered a consumable item and as such cannot be claimed.