

GROUP	NUMBER		
CAMPAIGN	20-01-001H		
DATE	MODEL(S)		
January, 2020	Sonata (DN8)		

SUBJECT:

SONATA (DN8) IAU IDENTIFICATION PROCEDURE SERVICE CAMPAIGN (T4L)

* IMPORTANT

*** Dealer Stock and Retail Vehicles ***

Dealers must perform this Service Campaign on all affected vehicles prior to customer retail delivery and whenever an affected vehicle is in the shop for any maintenance or repair.

When a vehicle arrives at the Service Department, access Hyundai Motor America's "Warranty Vehicle Information" screen via WEBDCS to identify open Campaigns.

Description: This bulletin describes the procedure to identify and retrieve the Unique Identification Numbers (UID) from the 20MY Sonata's Identity Authentication Unit (IAU) to enable Hyundai Digital Key.



Applicable Vehicles: All MY20 Sonata (DN8) Equipped with Smart User Feature.

Warranty Information:

Model	Op. Code	Operation	Op. Time	Causal Part	Nature Code	Cause Code
Sonata (DN8)	90CA17R0	IAU UID NUMBER	0.3 M/H	95590L0000	M72	ZZ3

You <u>must</u> attach a picture that <u>shows the UID number</u> to the campaign claim. Claims with an incorrect attachment may be subject to chargeback.

Service Procedure:

Press Engine Start Stop button.



Insert the GDS scan tool into the vehicle's Onboard Diagnostic II (OBD II) port.

NOTICE

The GDS scan tool must sit flush inside the OBD II port and the **Function light** must appear before proceeding further.

3. Turn on the GDS tablet and select **S/W Management**.

NOTICE

An **Error Message** will appear on GDS screen if the scan tool is not properly inserted in the OBD II port after selecting S/W Management





TSB #: 20-01-001H Page 2 of 4

4. After selecting S/W Management, a vehicle components list will appear on the GDS screen.


Select the Identity Authentication


5. After selecting Identity Authentication Unit, a drop down list will appear.

Select System Identification.

6. Caution. Do not touch the system buttons (like 'Back', 'Home', 'etc.') while performing this function. It may damage ECU pop-up message may appear.

Select OK.








TSB #: 20-01-001H Page 3 of 4

SUBJECT: SONATA (DN8) IAU IDENTIFICATION PROCEDURE

6. The system identification screen will appear.

Take a photo of the **UID Number**.

Press **OK** when complete.



- 7. Please **attach** the photo of the <u>UID</u>

 <u>Number</u> taken in step 6 to the campaign claim.
- 8. The service procedure is now complete.

TSB #: 20-01-001H Page 4 of 4