

2020-01-13

[illegible]

Release Notes

- Launch

Required Dealer Action

All module updates that this bulletin covers are updated using DT II (Digital Technician II) and TL-3 (Techlink 3) through the reflash tab.

DIGITAL TECHNICIAN II (PART NUMBER: HD-48650)

TECHLINK 3 (PART NUMBER: HD-48650-TL3)

Credit Procedure

NOTE

- Enter bulletin number into comment section of claim.
- If a previous update version has been installed, install **new** software version and submit a **new** claim as per Table 2.

Submit a warranty claim per Table 2 for all module updates that are covered under this bulletin.

Updated software versions must be installed in all applicable vehicles. Submit a claim per Table 2 to receive credit for performing these updates. The same credit table can be used for the same vehicle multiple times.

This credit procedure includes all labor time necessary to perform all software updates associated with this bulletin. Only submit 1 claim after all updates have been completed.

Table 2. Module Update

ITEM	DATA
Claim Type	PRD/Pre-Delivery or MC/Standard Claim
Problem Part Number	66000189
Quantity	Leave blank
Labor Code	2851
Time	0.4 h
Customer Concern Code	9203
Condition Code	2851