


PRODUCT INVESTIGATION ELECTRICAL

UPDATE

CAPABLE
OF GREAT
THINGS
PALM SPRINGS 2020

<p>Pop Noise From Audio Output</p> <p><u>Customer Voice:</u></p> <ul style="list-style-type: none">• Popping sound or crackling noise from the audio system while in use. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">• IMC module clipping sound due to large processing functions. <p><u>Status:</u></p> <ul style="list-style-type: none">• IMC Software 19C contains additional improvements and was released on December 11, 2019 for PATHFINDER, January 9,2020 for SDD and currently available wirelessly via TOPix.• If you should encounter a further complaint after 19C software has been installed, please submit a TA case for guidance. <p>A customer vehicle which was unresolved following the latest software release (North Carolina, Jaguar Raleigh) has now arrived back at Mahwah for further analysis and testing of an updated fix</p>	<p>16 – 20MY E-Pace, F-Pace, I-Pace, F-Type, XE, XF, XJ, Range Rover, RR Sport, RR Velar, RR Evoque, Discovery & Discovery Sport equipped with InControl Touch Pro</p> 
--	--