

Latest Vehicle Concern Fixes




Battery Junction Box Fuse Fasteners

Customer Voice:

- During PDI, two fasteners are found not to be installed in the battery junction box.

Technical Description:

- Vehicles that are non MHEV do not have fasteners or wiring installed. This is a normal condition and the connections do not require fasteners installed as non MHEV vehicles do not have a 48V battery equipped.



20MY Range Rover Evoque

