


Latest Vehicle Concern Fixes



Pop Noise From Audio Output	16 – 20MY E-Pace, F-Pace, I-Pace, F-Type, XE, XF, XJ, Range Rover, RR Sport, RR Velar, RR Evoque, Discovery & Discovery Sport equipped with InControl Touch Pro
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">• Popping sound or crackling noise from the audio system while in use. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">• IMC module clipping sound due to large processing functions. <p><u>Status:</u></p> <ul style="list-style-type: none">• IMC Software 19C contains additional improvements and was released on December 11, 2019 for PATHFINDER, January 9, 2020 for SDD and currently available wirelessly via TOPIx.• If you should encounter a further complaint after 19C software has been installed, please submit a TA case for guidance.	 A close-up photograph of two circular car audio speakers. The speakers have a mesh grille and are mounted on a dark, possibly leather or plastic, surface. The lighting is dramatic, highlighting the texture of the mesh and the surrounding material.

