



Retrofit Continental TPMS on Misconfigured Vehicle

Classification Campaign Bulletin **Section/Group** 17 - Electrical **Country/Region** All

Year 2014 **Model** Model S **Version** All

Bulletin Classification: This campaign bulletin addresses a known non-safety-related condition and provides recommended technical diagnosis and repair procedures. Apply this procedure to all vehicles in the affected VIN range listed. These instructions assume knowledge of motor vehicle and high voltage electrical component repairs, and should only be executed by trained professionals. Tesla assumes no liability for injury or property damage due to a failure to properly follow these instructions or repairs attempted by unqualified individuals.

This Service Document supersedes SB-15-17-009, dated 30-Nov-2015. Each content change is marked by a vertical line in the left margin. Discard the previous version and replace it with this one.

Condition

Some Model S vehicles were intended to have a Continental Tire Pressure Monitoring System (TPMS), but were manufactured with a Baolong TPMS.

Correction

Retrofit the Continental TPMS system.

NOTE: This document is only for vehicles that were manufactured with the incorrect TPMS. Do not use this bulletin to retrofit vehicles that are not within the affected VIN list. Service Engineering approval is not required for vehicles within the affected VIN list.

Correction Description	Correction	Time
Retrofit Continental TPMS To Match Vehicle Configuration - Module Only	S011517009	1.40
Retrofit Continental TPMS To Match Vehicle Configuration - Module And Harness	S021517009	3.35

Procedure

1. Perform the procedure described in SB-15-17-003, "Continental TPMS Retrofit".

NOTE: Do not use a correction code from SB-15-17-003. Use the appropriate correction code listed in this document.

Affected VIN(s) Affected Model S vehicles with a Baolong TPMS that were built between approximately September 4, 2014 and September 13, 2014.

NOTE: This is a simplified summary of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.

For feedback on the accuracy of this document, email ServiceBulletinFeedback@teslamotors.com.

