

[Next Unread Message](#)

View Message

Sent on	02	05	2020	Expires on	02	19	2020
From	Parts and Service Division						
Subject	Request for Visit: 2014-2019 MDX & TLX Fuel Leak at Fuel Joint Plpe						

PRIORITY/ACTION REQUIRED

To: All Acura Service Managers/Consultants
From: Technical Research & Support Group
RE: Request for Visit: 2014-2019 MDX & TLX Fuel Leak at Fuel Joint Plpe

**This message is solely directed to Acura dealership personnel; please handle accordingly.
Print this iN message and provide a copy to the Shop Foreman and all Service Advisors.**

Background

American Honda Motor Co., Inc. (AHM) is investigating certain 2014-2019 MDXs & 2015-2019 TLX with a client complaint of a fuel leak at the fuel joint pipe. To better understand the cause of this condition, AHM would like to inspect the vehicle prior to you attempting a repair of any kind.

Qualifiers

AHM is interested ONLY if the vehicle meets the following requirement:

1. Must trace the fuel leak to the fuel joint pipe at the fuel pump or the rail connection.
2. No repair has been attempted for this issue.
3. No prior history of the fuel joint pipe replacement.

Action Required

If you have or know of such a vehicle, please call the Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.