

Bulletin No.: PIC6399 Published date: 01/28/2020

## **Preliminary Information**

## PIC6399 Diagnostic Tip - Service Keyless Start message with B1446 SYM13 Interior Keyless Entry Antenna 3 High Signal

## <u>Models</u>

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:	
Dranu.			from	to	Engine.		
Cadillac	CT5	2020	ALL	ALL	ALL	ALL	
Involved Region or Country		North America					
Condition		A technician may find a Service Keyless Start message displayed . DTC B1446 SYM13 may be found relating to the Keyless Entry Antenna Rear Compartment					
Cause		The T10E Keyless Entry Antenna - Rear Compartment may not be mounted in its bracket.					

## Correction:

Inspect the T10E Keyless Entry Antenna - Rear Compartment for being loose or having fallen out of the bracket.



T10E Keyless Entry Antenna - Rear Compartment

Modified 01/28/2020 - Cr	eated on



© 2020 General Motors. All Rights Reserved.