

Published date: 01/31/2020

## **Preliminary Information**

PIP5689C 3.0L LM2 Diesel Engine With Malfunction Indicator Lamp Illuminated With One Or More DTCs Set - P214E, P2B60, P1010, P226D and/or P24B0

## Models

Brand:	Model:	Model Years:	VIN:		Engine	Transmissions:
			from	to	Engine:	Transmissions.
Chevrolet	Silverado 1500	2020	All	All	3.0 LM2	All
GMC	Sierra 1500	2020	All	All	3.0 LM2	All

Involved Region or Country:	North America
Condition:	Malfunction Indicator Lamp Illuminated with DTCs P2B60, P1010, P226D and/or P24B0 set.
Cause:	There is a software anomaly in the engine calibration that can falsely set DTCs P214E, P226D, P24B0, P2B60 or P1010.

## **Correction:**

Check to see if Service Update N192282970: Service Update - ECM and Reductant Control Modules is open.

If Service Update N192282970 is open, please perform it.

If there is an active P24B0, repair per Service Information.

If all of the above have been performed and any of the DTCs return refer to service information for diagnosis and repair.

## **Version History**

Version	4
	11/26/2019 - Created on.
Modified	12/12/2019 - Updated to add DTCs.
Modified	01/07/2020 - Updated to refer the technician to N192282970.
	01/31/2020 - Updated to add DTC P214E

















GENERAL MOTORS

© 2020 General Motors. All Rights Reserved.