



Technical Service Bulletin

91 MIB2+, DTC B200004 is stored in the information electronics control module

91 20 30 2058422/1 February 3, 2020.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q3	2019 - 2020	All	Not Applicable

Condition

Customer states:

- No customer concerns, it is found during PDI or any other diagnostic work.

Workshop findings:

The following DTC may be stored in the information electronics control module, J794 (address word 005F):

- **DTC B200004** (Ctrl. module faulty) with symptom code 22.

Technical Background

This DTC is a ghost DTC and is entered erroneously.

Production Solution

Not applicable.

Service

This DTC is a ghost DTC and is always entered erroneously.

Do not replace any components for this DTC since this will not resolve the customer's concern!

Warranty

This TSB is informational only and not applicable to any Audi Warranty.



Technical Service Bulletin

Additional Information

All part and service references provided in this TSB (2058422) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2020 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.