

94 Tail light or front indicator in bumper is cracked, broken, leaks, or does not work

94 20 19 2058420/1 February 3, 2020.

| Model(s)                    | Year        | VIN Range | Vehicle-Specific Equipment |
|-----------------------------|-------------|-----------|----------------------------|
| Q3                          | 2012 - 2018 | All       | Not Applicable             |
| Q5                          | 2009 - 2021 | All       | Not Applicable             |
| Q7                          | 2007 - 2021 | All       | Not Applicable             |
| Q8, Audi e-<br>tron quattro | 2019 - 2021 | All       | Not Applicable             |

#### **Condition**

#### **Customer states:**

• The turn signal in the **front** bumper (only on the Q7) is cracked/broken, leaks or does not work (bulb warning is displayed in the instrument cluster).

#### Or

 The turn signal in the rear bumper is cracked/broken, leaks or does not work (bulb warning is displayed in the instrument cluster).

### **Technical Background**

It is possible that the lamp may be damaged due to outside influence or forces applied to the lamp, bumper or underbody panels.

#### **Production Solution**

Not applicable.



#### **Service**

 Before replacing any components inspect the vehicle body and lamp(s) for damage that relates to outside influence (Figures 1 -5).



If necessary clean the parts before inspection as small cracks may be difficult to detect.



Figure 1. Turn signal in front bumper cracked.



Figure 2. Turn signal in front bumper cracked.





Figure 3. Turn signal in rear bumper cracked.



Figure 4. Turn signal in rear bumper scratched or cracked.





Figure 5. Turn signal in rear bumper cracked.

- 2. If damage relating to outside influence or force is found, this is not a warranty concern as it is considered consequential damage. In these cases, please explain the situation to the customer.
- 3. If there are no signs of outside influence, carry out standard diagnosis.

### Warranty

This damage is due to outside influence and is not covered by any Audi Warranty.

#### **Additional Information**

All part and service references provided in this TSB (2058420) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2020 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may



these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.