

Subject UA80/UB80 Transmission Side Cover Leak		Market USA
Service Category Drivetrain	Section Automatic Transmission/Transaxle	
Applicability Multiple Model UA80/UB80		

APPLICABLE VEHICLES

2018-2020	Highlander	2018-2019	Sienna
2019-2020	RAV4	2018-2020	Camry
2019-2020	Avalon		

CONDITION

Some 2018-2020 model year UA80/UB80 transmission equipped models may experience a leak from the Transmission Side Cover. This issue is currently under investigation. Please contact TAS if you have a vehicle that exhibits a leak from the Transmission Side Cover with no signs of damage or other conditions unrelated to regardless of miles or months in service.

RECOMMENDATIONS

Currently under investigation.

Please contact TAS if you have a vehicle that exhibits a leak from the Transmission Side Cover with no signs of damage or other conditions unrelated to regardless of miles or months in service. If it's a Sunday or holiday continue with diagnosis and repair, save all parts and details, contact TAS on the next available work day and review details with TAS engineer.

LINK REFERENCES

This Tech Tip does not contain any link references