

Tech Tip T-TT-0596-20

January 29, 2020

Creaking Noise When Turning Steering Wheel

USA

Suspension

Front Suspension

2020 Avalon/Avalon HV/Camry/Camry HV

APPLICABLE VEHICLES

2020	Avalon HV	2020	Camry	
2020	Camry HV	2020	Avalon	

CONDITION

Creaking noise during turns (or turning steering wheel) coming from front strut area.

- 1) Vehicles under 5,000 miles
- 2) Refer to the attached video as an example of the noise



RIMG1638.wmv

RECOMMENDATIONS

After noise is confirmed from front strut area stop and do not attempt any repairs.

Please contact your FPE or FTS for further instruction.

If it is a Sunday or holiday, continue with diagnosis and repair, save all parts and details (including pictures), and contact TAS at the next available opportunity.

LINK REFERENCES

This Tech Tip does not contain any link references