

Notice Information

Ref	13502
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Aftersales Manager, Service Leader / Advisor, Accounts / Admin
Subject:	Service/Technical

TOL NOTICE (US&CAN) – January 28, 2020
13502-SVC

TOL Ref. #

New Diagnostic Software Available for Download

Diagnostic software version 2020-2 is now available to download. Dealers should download this update from your Triumph Diagnostic Software page under the Service/Technical menu and begin using immediately.

- Please ensure all new bikes have the latest software downloaded at PDI.
- Please ensure all bikes being serviced have the latest software downloaded.
- Please ensure all relevant staff are informed of this update.

**** New password (case sensitive): Triple25**

SUMMARY OF CHANGES:

1 **New Software Functionality:**

As the one millionth VIN has now been built, the last six digits of the VIN has changed to an alpha/numeric format starting with two alphabetical characters and followed by four numeric digits (AA0001, AA000...). Background TDT functionality has been updated to support the new VIN format.

2 **Engine ECM Calibrations:**

Bonneville Bobber TFC

- 030266-02
- 030267-02
- 030268-02

Scrambler 1200 XC

- 030249-03
- 030250-03
- 030251-03
- 030252-03
- 030278-03

Scrambler 1200 XE

- 030253-03
- 030254-03
- 030255-03
- 030256-03

Thrupton RS

- 031006-02
- 031007-02
- 031010-02

3 **Chassis ECM Calibrations:** None

Tiger 1200 Alpine

- INST00098
- INST00099

4 **Instrument ECM Calibrations:**

Tiger 1200 Desert

- INST00100
- INST00101

5 **Connectivity Module Calibrations:** None

6 **Keyless ECM Calibrations:** None

7 **New ECU Unlock Codes:** None

8 **Calibration Description Corrections:** None

9 **Bug Fix(es):** None

The following items are not supported for Thrupton RS models:

10 **Known Issues In This Release:**

- Autoscan

If you have any questions, please contact Triumph Customer Support at (888) 284-6288.